telatemp New Tamperproof Transit Thermometer

THIRD-GENERATION CHART RECORDER PERMANENTLY LOGS STORAGE OR TRANSIT TEMPERATURES.

LOWER-COST AND MORE COMPACT, PRINTS ELAPSED TIME VS. TEMPERATURE WITH NIST TRACEABLE ACCURACY.

T he new, third-generation Tamperproof Transit Thermometer is rugged enough for over-the-highway distribution of perishable or sensitive products, versatile enough for almost any application, and provides impartial third-party documentation for both the shipper and receiver. The self-contained unit is shipped ready-to-use and requires no computer hook-up or outside electrical power. Its tough ABS case is durable, yet the operating accuracy is ±2.0ºF. (±1.1ºC) full range. Models are available in 10-, 40-, 75- and 90-day recording ranges.

Measuring 5.25" L by 2.5" H by 3.5" W, the newest generation thermometer is more compact. With its lower price, this unit saves both space and money.

Whether you're sending foods, pharmaceuticals, chemicals, films, materials, medical devices or clinical test kits, this disposable recorder will assure quality by permanently recording the temperature during storage or transit.

SPECIFICATIONS

Temperature accuracy	±2.0ºF (±1.1ºC) full range
Temperature resolution	1º F/C
Activation	Tamperproof pull-out tab
Chart resolution	10 day 2.50 inches per day
	40 day .73 inches per day
	75 day .73 inches per day
	90 day .73 inches per day
Power/Shelf life	1.5 volt AA battery/one year from purchase date
Validation	NIST Traceable; Conformity European (CE)
Tamper-proof security seal	Factory sealed
Notice of shipment	Three-part water-proof notice attached
Enclosure	ABS plastic
Dimensions/weight	7.2 ounces/5.25"L by 2.50"H by 3.50"W

Specifications subject to change without notice.

ORDERING INFORMATION

LTR3-10, LTR3-40, LTR3-75
Chill/Freezer Temperature range   -20ºF to 100ºF/-29ºC to 38ºC

HTR3-40 and HTR3-90
High Temperature range   -10ºF to 130ºF/-12ºC to 54ºC

telatemp Transit Thermometer
40 Day Chill/Freezer CE

Telatemp Corporation • Fullerton, CA 92831
USA • (714) 879-2901 • FAX (714) 870-8136
customerservice@telatemp.com

S/N:1705252S
Driver Signature:
Carrier:
Vessel:
Shipper:
Receiver:
Order#:
Product:
Date:
Time:
2 COPY NOTICE

Simple to operate:
1. Fill out the shipping information.
2. Pull tab from the side of the instrument. You can verify operation by observing movement in the viewing window next to the tab.
3. Install by removing liner from adhesive tape on back of instrument. Secure to a suitable smooth, dry surface.

Chart removal:
1. Cut security seals and open by pressing latch at top of instrument.
2. Grasp chart with thumb and forefinger and pull straight up.