

A10 Filament & Heater Repair


Agilent Technologies FILAMENT REPAIR

The Agilent Technologies filaments can be repaired by S.I.S.™ We will completely clean the assembly and replace the rhenium filament wire or coil.

5972/5973 Filament




5971/GCD Filament



Ignitor Assembly Filament



5975 Filament



5973 CI Filament



► *Tech Tip* For New Filaments, See Pg. A21


NEW Agilent Technologies FILAMENTS

The low cost of these filaments makes them not repairable. They are only available as new replacement filaments. See Agilent section for pricing. For other new Agilent filaments see our new filament section of this catalog. (A21-A22)




Filaments are aligned and spotwelded into place

HPF4 - 5970 Filament



HPF2 - 5989 Engine Filament



HPF1 Filament



HPF3 Filament

