

Incos™ 500, 50B and XL Temperature Sensors

Thermo MAT#55000-60085



Part No.	Thermo No.	Description	Price ea.	Qty. 6 or more Price ea.
PRT6	55000-60085	Temp. Sensor for Incos 500, 50B		


Incos 500, 50B and XL Heaters



Part No.	Description	Price ea.
SC1812B	Incos 500, 50B Source Heater	

Incos 500, Incos 50B and Incos XL Filament

Thermo MAT #55000-60080



Part No.	Description	Price ea.
FF50B	Incos 500, 50B Filament	
	Six or more	

Incos® is a registered trademark of Thermo Fisher Scientific Corp.

Ceramic Insulators for Incos 50 Source

Part No.	Finnigan No.	O.D.	I.D.	Thick.	Price/ ea.
Z31	55000-20014	.087"	.063"	.160"	
Z32	55000-20065	.087"	.063"	.760"	
Z5	07504-21108	.156"	.094"	.030"	
Z26	30004-20020	.156"	.093"	.100"	

Incos 50 Temperature Sensor

Thermo MAT #55000-60068



Part No.	Thermo No.	Description	Price ea.	Qty. 6 or more Price ea.
PRT5	55000-60068	Incos 50 Temp. Sensor		


Incos 50 Source Heater

Thermo MAT #55000-98005



Part No.	Thermo No.	Description	Price ea.
SC1812	55000-98005	Incos 50 Source Heater	

Incos 50 Stainless Steel or Ceramic Filament



Part No.	Description	Price ea.
SF5100	Incos 50 Metal Filament	
	Six or more	
FF50	Incos 50 Ceramic Filament	
	Six or more	

Thermo* Jet Separator Repair

All models of jet separators can be repaired if the side arms become damaged or broken. Jets to be repaired must have at least 5/8" glass arm extending past the main body in order to be repaired. Jets repaired with less than 5/8" cannot be guaranteed. We can also clean most clogged jets. S.I.S. assumes no responsibility for jets damaged during the unclogging procedure.

Part No.	Description	Price ea.
REP71	Repair One Jet Separator Arm	
REP72	Repair Two Jet Separator Arms	
REP73	Repair Three Jet Separator Arms	
REP7C	Clean Jet Separator-price per Jet	

Incos 50B Transfer Line Repair

The long transfer lines between the GC and the Incos 50B mass spectrometers can be repaired by S.I.S. The heater, thermocouple and fittings can be repaired or replaced. Please send in your transfer line for evaluation. We will examine it quickly, call you with a price for repair and then in a minimum turnaround time repair it for you.

*When "Thermo" is indicated, it is intended to imply "Thermo Fisher Scientific Corp"